



FEDERAL AVIATION ADMINISTRATION
AIRWORTHINESS DIRECTIVES
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS,
BALLOONS, & AIRSHIPS

BIWEEKLY 2000-06

This electronic copy may be printed and used in lieu of the FAA biweekly paper or microfiche copy.

U.S. Department of Transportation
Federal Aviation Administration
Regulatory Support Division
Airworthiness Programs Branch, AFS-610
P. O. Box 26460
Oklahoma City, OK 73125-0460
FAX 405-954-4104

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; + - See AD for additional information

Biweekly 2000-01

99-27-02		Cessna	170B, 172, 172A, 172B, 172C, 172D, 172E, 172F, 172G, +
99-27-12	S 99-26-13	Agusta	Rotorcraft: A109A and A109A II

Biweekly 2000-02

98-19-15 R1	R 98-19-15	Fairchild	SA226-T, SA226-T(B), SA226-AT, SA226-TC +
99-26-04		Kaman	Rotorcraft: K-1200
2000-01-06		Rolladen	Glider: LS6-c Sailplane
2000-01-09		General Electric	Engine: CJ610, CF700
2000-01-10	S 98-08-07	Pilatus	PC-7
2000-01-11	S 99-17-07	Eurocopter Deutschland	Rotorcraft: MBB-BK 117 A-1, A-3, A-4, B-1, B-2, C-1
2000-01-16	S 75-23-08 R5	Cessna	T310P, T310Q, T310R, 320, 320A, 320B, 320C, 320D +
2000-01-19		Eurocopter Deutschland	Rotorcraft: EC 135 P1, EC 135 T1
2000-02-12	E	Bell	Rotorcraft: 407

Biweekly 2000-03

2000-02-09		Agusta	Rotorcraft: AB412
2000-02-14	S 98-13-10	Cessna	182S
2000-02-16		Short Brothers	SC-7 Series 2 and SC-7 Series 3
2000-02-32	S 98-12-21	Eurocopter France	Rotorcraft: SA.315B

Biweekly 2000-04

99-25-08		MD Helicopters	Rotorcraft: 500N
2000-02-12		Bell	Rotorcraft: 407
2000-02-25		Mitsubishi	MU-2B Series
2000-02-26		Harbin	Y12 IV
2000-02-27		Empresa	EMB-110P1 and EMB-110P2
2000-02-28		Aerospace Technologies	N22B and N24A
2000-02-29		Socata	TBM 700
2000-02-30		Twin Commander	600 Series
2000-02-31		Pilatus	PC-12 and PC-12/45
2000-03-06		Eurocopter France	Rotorcraft: SE 3130, SA 3180, SE 313B, SA 318B, +
2000-03-17	S 97-23-01	Fairchild	SA226 and SA227 Series
2000-03-18		Partenavia	AP68TP 300 "Sartacus" and AP68TP 600 "Viator"
2000-03-19		Industrie Aeronautiche	Piaggio P-180
2000-04-01		Cessna	172R, 172S, 182S, 206H, and T206H
2000-04-10		Hoffmann	Propeller: HO27() and HO4/27 Series
2000-04-12		Cameron	Balloon: CB2380 and CB2383

Biweekly 2000-05

98-21-21	R1	Bob Fields Aerocessories	Appliance: Electric inflatable door seals
2000-03-09		Cessna	560 Series
2000-04-16		Alexander Schleicher	ASH 25M and ASH 26E sailplanes
2000-04-26		Alexander Schleicher	ASW-27 sailplanes
2000-05-11		Eurocopter France	Rotorcraft: SA.315B, SA.316B, SA.316C, SA 318B, +

Biweekly 2000-06

2000-04-20		Bell	Rotorcraft: 407
2000-04-21		MD Helicopters	Rotorcraft: MD600N
2000-04-24		Honeywell International	Appliance: Auxiliary Power Units
2000-04-25		Bell	Rotorcraft: 407
2000-05-15		Eurocopter France	Rotorcraft: AS355N
2000-05-16		Sikorsky	Rotorcraft: S-61
2000-05-17	S 99-19-23	Eurocopter France	Rotorcraft: EC 120B

SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

AD No.	Information	Manufacturer	Applicability
--------	-------------	--------------	---------------

Info: E - Emergency; COR - Correction; S - Supersedes; R - Revision; + - See AD for additional information

Biweekly 2000-06...Cont'd

2000-05-23	Ayres	S-2R, S2R-G1, S2R-G5, S2R-G6, S2R-G10, S2R-R3S +
2000-05-24	Honeywell International	Appliance: KAP 140 or KFC 225 autopilot system
2000-06-01	Cessna	150F, 150G, 150H, 150J, 150K, 150L, 150M, A150K, +
2000-06-02	Dornier	228-100, 228-101, 228-200, 228-201, 228-202, +
2000-06-03	Bombardier	DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300
2000-06-04	Fairchild	SA226-T, SA226-AT, SA226-T(B), SA227-AT, +
2000-06-06	The New Piper	PA-31, PA-31-300, PA-31-325, PA-31-350, PA-31P, +

**BELL HELICOPTER TEXTRON CANADA
AIRWORTHINESS DIRECTIVE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

2000-04-20 BELL HELICOPTER TEXTRON CANADA: Amendment 39-11603. Docket No. 98-SW-64-AD.

Applicability: Model 407 helicopters, serial numbers 53000 through 53266, inclusive, certificated in any category.

NOTE 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required within 300 hours time-in-service, unless accomplished previously.

To prevent intermittent loss of hydraulic pressure to the flight controls and subsequent loss of control of the helicopter, accomplish the following:

(a) Remove the hydraulic relief valve (valve), part number (P/N) 206-076-036-101, and replace it with an airworthy valve, P/N 206-076-036-105, in accordance with the Accomplishment Instructions in Bell Helicopter Textron Alert Service Bulletin No. 407-98-20, dated July 3, 1998.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Regulations Group.

NOTE 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Regulations Group.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(d) The modification shall be done in accordance with the Accomplishment Instructions in Bell Helicopter Textron Alert Service Bulletin No. 407-98-20, dated July 3, 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Bell Helicopter Textron Canada, 12,800 Rue de l'Avenir, Mirabel, Quebec JON1LO, telephone (800) 463-3036, fax (514) 433-0272. Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(e) This amendment becomes effective on April 5, 2000.

NOTE 3: The subject of this AD is addressed in Transport Canada (Canada) AD CF-98-28, dated August 31, 1998.

FOR FURTHER INFORMATION CONTACT:

Robert McCallister, Aerospace Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, Fort Worth, Texas 76193-0170, telephone (817) 222-5121, fax (817) 222-5961.

Issued in Fort Worth, Texas, on February 22, 2000.

Henry A. Armstrong, Manager, Rotorcraft Directorate, Aircraft Certification Service.

**MD HELICOPTERS, INC.
AIRWORTHINESS DIRECTIVE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

2000-04-21 MD HELICOPTERS, INC.: Amendment 39-11604. Docket No. 99-SW-54-AD.

Applicability: Model MD600N helicopters, serial numbers with a prefix of "RN" 003 through 045, certificated in any category.

NOTE 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent fuel starvation of the engine while the fuel gage indicates fuel remaining in the tank, engine flameout, and a subsequent forced landing, accomplish the following:

(a) Within 100 hours time-in-service, verify that the internal fuel hose connections have been properly installed in accordance with either Method A or Method B of the Accomplishment Instructions of MD Helicopters Service Bulletin SB 600N-025, dated July 2, 1999. Prior to further flight, make any necessary corrections.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Los Angeles Aircraft Certification Office.

NOTE 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Los Angeles Aircraft Certification Office.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(d) The inspections shall be done in accordance with either Method A or Method B of the Accomplishment Instructions of MD Helicopters Service Bulletin SB 600N-025, dated July 2, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from MD Helicopters Inc., Attn: Customer Support Division, 5000 E. McDowell Rd., Mail Stop M615-GO48, Mesa, Arizona 85215-9797, telephone 1-800-388-3378 or 480-891-6342, fax 480-891-6782. Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(e) This amendment becomes effective on April 5, 2000.

FOR FURTHER INFORMATION CONTACT:

Elizabeth Bumann, Aerospace Engineer, FAA, Los Angeles Aircraft Certification Office, 3960 Paramount Blvd., Lakewood, California 90712-4137, telephone (310) 627-5265; fax (310) 627-5210.

Issued in Fort Worth, Texas, on February 22, 2000.

Henry A. Armstrong, Manager, Rotorcraft Directorate, Aircraft Certification Service.

**HONEYWELL INTERNATIONAL
AIRWORTHINESS DIRECTIVE
APPLIANCE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

2000-04-24 HONEYWELL INTERNATIONAL (formerly AlliedSignal Inc.): Amendment 39-11607.
Docket 99-NE-34-AD.

Applicability: Honeywell International (formerly AlliedSignal Inc.) 36-300(A), 36-280(B), and 36-280(D) series Auxiliary Power Units (APUs), with load compressor impellers, part numbers (P/Ns) 3822270-4, or 3822270-5, installed. These APUs are installed on but not limited to Airbus Industrie A319, A320, and A321 series; Boeing 737-300, -400, -500 series; and McDonnell Douglas MD-80 series airplanes.

NOTE 1: This airworthiness directive (AD) applies to each APU identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For APUs that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

NOTE 2: The presence or absence of the letters "GTCP" preceding the model series does not affect the applicability of this AD to the specified model APUs.

NOTE 3: AD 92-21-05 requires that all APUs with load compressor impellers, P/Ns 3822270-1 or 3822270-3, be reworked to the -4 configuration.

Compliance: Required as indicated, unless accomplished previously.

To prevent an uncontained APU failure and damage to the airplane, accomplish the following:

Load Compressor Impellers, P/N 3822270-4

(a) For APUs with load compressor impellers, P/N 3822270-4, at the next shop visit, or within 6 months after the effective date of this AD, whichever occurs first, accomplish either of the following:

(1) Install an external load compressor containment shield in accordance with AlliedSignal Inc. Service Bulletins (SBs) No. GTCP36-49-7471, dated April 20, 1999, GTCP36-49-7472, dated March 31, 1999, or GTCP36-49-7473, dated March 31, 1999, as applicable; or

(2) Install load compressor impeller, P/N 3822270-5.

Load Compressor Impellers, P/N 3822270-5

(b) For APUs with load compressor impellers, P/N 3822270-5, install an external load compressor containment shield within one year after the effective date of this AD, or prior to the impeller exceeding 26,000 cycles-since-new (CSN), whichever occurs later, in accordance with AlliedSignal Inc. SBs No. GTCP36-49-7471, dated April 20, 1999, GTCP36-49-7472, dated March 31, 1999, or GTCP36-49-7473, dated March 31, 1999, as applicable.

NOTE 4: Operators may use their own FAA-approved tracking system for determining load compressor impeller cyclic count in lieu of the procedure described in the AlliedSignal Inc. SBs referenced in this AD.

Cyclic Limit without External Containment Shield

(c) Following one year after the effective date of this AD, operators cannot operate with a load compressor, P/N 3822270-5, installed, past 26,000 cycles unless they have installed an external load compressor containment shield.

Definition

(d) For the purpose of this AD, a shop visit is defined as when the APU is inducted into a shop for any reason.

Alternative Methods of Compliance

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Los Angeles Aircraft Certification Office. Operators shall submit their request through an appropriate FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Los Angeles Aircraft Certification Office.

NOTE 5: Information concerning the existence of approved alternative methods of compliance with this airworthiness directive, if any, may be obtained from the Los Angeles Aircraft Certification Office.

Ferry Flights

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

2000-04-24

Incorporation by Reference

(g) The actions required by this AD shall be done in accordance with the following AlliedSignal Inc. SBs: GTCP36-49-7471, dated April 20, 1999, GTCP36-49-7472, dated March 31, 1999, and GTCP36-49-7473, dated March 31, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Honeywell International, Inc., Attn: Data Distribution, M/S 64-3/2101-201, PO Box 29003, Phoenix, AZ 85038-9003; telephone 602-365-2493, fax 602-365-5577. Copies may be inspected at the FAA, New England Region, Office of the Regional Counsel, 12 New England Executive Park, Burlington, MA; or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

(h) This amendment becomes effective on May 8, 2000.

FOR FURTHER INFORMATION CONTACT:

Roger Pesuit, Aerospace Engineer, Los Angeles Aircraft Certification Office, FAA, Transport Airplane Directorate, 3960 Paramount Blvd., Lakewood, CA 90712-4137; telephone 562-627-5251, fax 562-627-5210.

Issued in Burlington, Massachusetts, on February 25, 2000.

Jay J. Pardee, Manager, Engine and Propeller Directorate, Aircraft Certification Service.

**BELL HELICOPTER TEXTRON CANADA
AIRWORTHINESS DIRECTIVE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

2000-04-25 BELL HELICOPTER TEXTRON CANADA: Amendment 39-11068. Docket No. 98-SW-70-AD.

Applicability: Model 407 helicopters, serial numbers 53000 through 53228, with door latch assemblies, part number (P/N) 20898-401, -402, -405, and -406, installed, certificated in any category.

NOTE 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required within 100 hours time-in-service, unless accomplished previously.

To prevent a door latch rod assembly from disengaging from the door handle and preventing helicopter occupants from opening the door, accomplish the following:

(a) Modify each door latch assembly, P/N 20898-401, -402, -405, and -406, in accordance with the Accomplishment Instructions in Bell Helicopter Textron Alert Service Bulletin No. 407-98-18, dated May 27, 1998.

(b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Regulations Group.

NOTE 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Regulations Group.

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(d) The modification shall be done in accordance with Bell Helicopter Textron Alert Service Bulletin No. 407-98-18, dated May 27, 1998. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Bell Helicopter Textron Canada, 12,800 Rue de l'Avenir, Mirabel, Quebec JON1LO, telephone (800) 463-3036, fax (514) 433-0272. Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(e) This amendment becomes effective on April 12, 2000.

NOTE 3: The subject of this AD is addressed in Transport Canada (Canada) AD No. CF-98-19, dated July 28, 1998.

FOR FURTHER INFORMATION CONTACT:

Sharon Miles, Aerospace Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, Fort Worth, Texas 76193-0110, telephone (817) 222-5122, fax (817) 222-5961.

Issued in Fort Worth, Texas, on February 24, 2000.

Henry A. Armstrong, Manager, Rotorcraft Directorate, Aircraft Certification Service.

**EUROCOPTER FRANCE
AIRWORTHINESS DIRECTIVE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

2000-05-15 EUROCOPTER FRANCE: Amendment 39-11625. Docket No.99-SW-87-AD.

Applicability: Model AS355N helicopters, certificated in any category.

NOTE 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required within 10 hours time-in-service (TIS) and thereafter at intervals not to exceed 100 hours TIS, unless accomplished previously.

To prevent separation of an engine exhaust pipe ejector from the helicopter, which could result in a tail rotor strike and subsequent loss of control of the helicopter, accomplish the following:

(a) In accordance with paragraph BB of Eurocopter France Service Telex No. 00095, dated October 27, 1999 (Telex) that references Service Telex No. 01.00.45, visually inspect the:

- (1) 4 engine exhaust pipe ejector attachment lugs (lugs) for any crack;
- (2) starter-generator (S-G) shaft for radial play;
- (3) S-G attachment flange for any crack; and
- (4) S-G attachment half-clamps for any crack.

(b) If a crack is found in either the lugs, the S-G attachment flange, or the S-G attachment half-clamps, repair or replace the cracked part with an airworthy part prior to further flight.

(c) If radial play is discovered in the S-G, replace it with an airworthy S-G prior to further flight.

(d) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Rotorcraft Directorate.

NOTE 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Regulations Group.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(f) The inspections and replacements, if necessary, shall be done in accordance with Eurocopter France Service Telex No. 00095, dated October 27, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, Texas 75053-4005, telephone (972) 641-3460, fax (972) 641-3527. Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(g) This amendment becomes effective on March 31, 2000.

NOTE 3: The subject of this AD is addressed in Direction Generale De L'Aviation Civile (France) AD 1999-469-058(A), dated December 1, 1999.

FOR FURTHER INFORMATION CONTACT:

Shep Blackman, Aerospace Engineer, FAA, Rotorcraft Directorate, Rotorcraft Standards Staff, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222-5296, fax (817) 222-5961.

Issued in Fort Worth, Texas, on March 6, 2000.

Henry A. Armstrong, Manager, Rotorcraft Directorate, Aircraft Certification Service.

**SIKORSKY AIRCRAFT CORPORATION
AIRWORTHINESS DIRECTIVE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

2000-05-16 SIKORSKY AIRCRAFT CORPORATION: Amendment 39-11626. Docket No. 99-SW-61-AD.

Applicability: Model S-61 helicopters with pylon, part number (P/N) S6120-76265-001 or S6120-76266-507, installed, certificated in any category.

NOTE 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (b) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent structural failure due to a crack or corrosion of pylon upper and lower hinge web fittings (web fittings), P/NS6120-76261-012, -013 (upper) or S6120-76262-012, -013 (lower), and subsequent loss of control of the helicopter, accomplish the following:

- (a) Within 25 hours time-in-service (TIS),
 - (1) Determine the alloy-temper of the web fittings in accordance with Sikorsky Aircraft Corporation Alert Service Bulletin No. 61B20-33, dated September 3, 1999 (ASB), Accomplishment Instructions, paragraph 3.A.
 - (2) Prepare the web fittings for inspection in accordance with the ASB Accomplishment Instructions, paragraph 3.B.
 - (3) Inspect the web fitting in accordance with the ASB Inspection Plan, Chart A, and the Accomplishment Instructions, paragraphs 3.C., 3.D, and 3.E. Nicks, scratches, corrosion pitting or prior rework beyond the limits specified in paragraph 3.C.(5) require approval by the FAA.
 - (4) Repair or replace web fittings, as necessary, in accordance with the ASB Accomplishment Instructions, paragraph 3.C.(3) through (6). Nicks, scratches, corrosion pitting, or prior rework beyond the limits specified in paragraph 3.C.(5) require approval by the FAA.
 - (5) If replacing an unairworthy web fitting with an airworthy web fitting, replace it in accordance with the ASB Accomplishment Instructions, paragraph 3.F., prior to further flight.
 - (6) Create a log card for the pylon, if none exists. Make an entry on the log card or equivalent record implementing recurring inspection intervals in accordance with Chart A of the ASB.
- (b) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Boston Aircraft Certification Office, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Boston Aircraft Certification Office.

NOTE 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Boston Aircraft Certification Office.

- (c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.
- (d) The inspection, repair, and replacement shall be done in accordance with the Inspection Plan, Chart A, and the Accomplishment Instructions of Sikorsky Aircraft Corporation Alert Service Bulletin No. 61B20-33, dated September 3, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Sikorsky Aircraft Corporation, Attn: Manager, Commercial Tech Support, 6900 Main Street, P.O. Box 9729, Stratford, Connecticut 06497-9129, phone (203) 386-7860, fax (203) 386-4703. Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.
- (e) This amendment becomes effective on March 30, 2000.

FOR FURTHER INFORMATION CONTACT: Brian K. Murphy, Aerospace Engineer, ANE-150, 12 New England Executive Park, Burlington, MA 01803, telephone (781) 238-7739, fax (781) 238-7199.

Issued in Fort Worth, Texas, on March 6, 2000.

Henry A. Armstrong, Manager, Rotorcraft Directorate, Aircraft Certification Service.

**EUROCOPTER FRANCE
AIRWORTHINESS DIRECTIVE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

2000-05-17 EUROCOPTER FRANCE: Amendment 39-11627. Docket No. 99-SW-85-AD. Supersedes AD 99-19-23, Amendment 39-11343, Docket No. 99-SW-53-AD.

Applicability: Model EC 120B helicopters with engine coupling tube (coupling tube), part number (P/N) C631A1002101, installed, certificated in any category.

NOTE 1: This AD applies to each helicopter identified in the preceding applicability provision, regardless of whether it has been otherwise modified, altered, or repaired in the area subject to the requirements of this AD. For helicopters that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (e) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated, unless accomplished previously.

To prevent coupling failure, loss of engine drive, and a subsequent forced landing, accomplish the following:

(a) Within 10 hours time-in-service (TIS), and thereafter at intervals not to exceed 10 hours TIS except when required to perform the inspection required by paragraph (b) of this AD while each coupling tube, P/N C631A1002101, is installed, inspect for any crack in accordance with the Accomplishment Instructions, paragraph 2.B.1., of Eurocopter Service Bulletin No. 05-001, dated September 23, 1999 (SB 05-001).

(b) Within 10 hours TIS, and thereafter at intervals not to exceed 30 hours TIS, after each coupling tube, P/N C631A1002101, has been removed, inspect for any crack in accordance with paragraph 2.B.2. of SB 05-001.

NOTE 2: Operators are not required to inform the manufacturer when a crack is found.

(c) When a crack is found as a result of the inspections conducted in accordance with either paragraph (a) or (b) of this AD, or by March 31, 2000, whichever occurs first, replace the coupling tube with a reinforced, airworthy coupling tube, P/N C631A1101101, and replace the engine mount fittings in accordance with Eurocopter Service Bulletin No. SB 63-001, dated November 10, 1999, using new, airworthy, engine mount fitting components to replace the following:

- Teflon spacer, P/N C714A1010208;
- Black-colored spring washers, 10.2 x 28 Type-C;
- Blue-colored hinge yoke, P/N C714A1010212; and
- Special washer, P/N C714A1010213.

NOTE 3: Eurocopter Service Bulletin No. 01-002 pertains to unairworthiness of the four engine mount fitting components listed in paragraph (c) of this AD.

(d) Installing the reinforced, airworthy coupling tubes, P/N C631A1101101, and replacing the engine mount fitting components using new, airworthy, engine mount fitting components, as specified in paragraph (c) of this AD, constitutes terminating action for the requirements of this AD.

(e) An alternative method of compliance or adjustment of the compliance time that provides an acceptable level of safety may be used if approved by the Manager, Regulations Group, Rotorcraft Directorate, FAA. Operators shall submit their requests through an FAA Principal Maintenance Inspector, who may concur or comment and then send it to the Manager, Regulations Group.

NOTE 4: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Regulations Group.

(f) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the helicopter to a location where the requirements of this AD can be accomplished.

(g) The inspections and modifications shall be done in accordance with the Accomplishment Instructions, paragraph 2.B.1., of Eurocopter Service Bulletin No. 05-001, dated September 23, 1999; Eurocopter Service Bulletin No. 63-001, dated November 10, 1999; and Eurocopter Service Bulletin No. 01-002, dated December 23, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from American Eurocopter Corporation, 2701 Forum Drive, Grand Prairie, Texas 75053-4005, telephone (972) 641-3460, fax (972) 641-3527. Copies may be inspected at the FAA, Office of the Regional Counsel, Southwest Region, 2601 Meacham Blvd., Room 663, Fort Worth, Texas; or at the Office of the Federal Register, 800 North Capitol Street, NW., suite 700, Washington, DC.

(h) This amendment becomes effective on March 27, 2000.

NOTE 5: The subject of this AD is addressed in Direction Generale de L'Aviation Civile (France) AD 1999-349-002(A) R2, dated November 3, 1999 and AD 2000-058-003(A), dated February 9, 2000.

FOR FURTHER INFORMATION CONTACT:

Shep Blackman, Aerospace Engineer, Regulations Group, Rotorcraft Directorate, FAA, 2601 Meacham Blvd., Fort Worth, Texas 76137, telephone (817) 222-5296, fax (817) 222-5961.

Issued in Fort Worth, Texas, on March 6, 2000.

Henry A. Armstrong, Manager, Rotorcraft Directorate, Aircraft Certification Service.

**AYRES CORPORATION
AIRWORTHINESS DIRECTIVE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

2000-05-23 AYRES CORPORATION: Amendment 39-11633; Docket No. 99-CE-57-AD.

Applicability: The following airplane models, all serial numbers, certificated in any category, that have at least one main landing gear fuselage attach bolt (that is drilled with a grease fitting), part number 21418T001 or 21418T005 (or FAA-approved equivalent part number):

Models

S-2R, S2R-G1, S2R-G5, S2R-G6, S2R-G10, S2R-R3S, S2R-T11, S2R-T15, S2R-T34, S2R-T45, S2R-T65, S2R-R1340, S2R-R1820, S2RHG-T34, and S2RHG-T65.

NOTE 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (d) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated in the body of this AD, unless already accomplished.

To prevent collapse of the main landing gear caused by cracked main landing gear fuselage attach bolts, which could result in main landing gear collapse with possible wing fuel tank rupture and consequent fire, accomplish the following:

(a) Within the next 100 hours time-in-service (TIS) after the effective date of this AD, replace each main landing gear fuselage attach bolt that is drilled with a grease fitting with an undrilled (no grease access) attach bolt, part number AN10-33 or NAS6610-42D (or FAA-approved equivalent part number). Accomplish this replacement in accordance with both Ayres Service Bulletin No. SB-AG-42, dated June 16, 1999, and the applicable maintenance manual.

(b) As of the effective date of this AD, no person may install, on any affected airplane, a main landing gear fuselage attach bolt (that is drilled with a grease fitting), part number 21418T001 or 21418T005 (or FAA-approved equivalent part number).

(c) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

(d) An alternative method of compliance or adjustment of the compliance times that provides an equivalent level of safety may be approved by the Manager, Atlanta Aircraft Certification Office (ACO), One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30349. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Atlanta ACO.

NOTE 2: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Atlanta ACO.

(e) The replacements required by this AD shall be done in accordance with Ayres Service Bulletin No. SB-AG-42, dated June 16, 1999. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from Ayres Corporation, P.O. Box 3090, One Ayres Way, Albany, Georgia 31706-3090. Copies may be inspected at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

(f) This amendment becomes effective on May 5, 2000.

FOR FURTHER INFORMATION CONTACT:

Satish Lall, Aerospace Engineer, FAA, Atlanta Aircraft Certification Office, One Crown Center, 1895 Phoenix Boulevard, suite 450, Atlanta, Georgia 30349; telephone: (770) 703-6082; facsimile: (770) 703-6097.

Issued in Kansas City, Missouri, on March 7, 2000.

Michael Gallagher, Manager, Small Airplane Directorate, Aircraft Certification Service.

HONEYWELL INTERNATIONAL INC
AIRWORTHINESS DIRECTIVE
APPLIANCE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS

2000-05-24 HONEYWELL INTERNATIONAL INC.: Amendment 39-11634; Docket No. 2000-CE-11-AD.

(a) What aircraft are affected by this AD?: Any aircraft, certificated in any category, that is equipped with a Honeywell KAP 140 or KFC 225 autopilot system and incorporates any autopilot servo actuator referenced in the Honeywell service information and the chart presented below. AlliedSignal Avionics Inc. manufactured the KAP 140 and KFC 225 autopilot systems before transferring the design data to Honeywell:

Service Bulletin No.:	Date:	Applies To:
SB KS 270C-4 ALERT Part number (P/N): 600-01514-0041	Revision 1: February/2000	KS 270C Pitch Servo Actuators, P/N 065-00178-XXXX (all versions), serial numbers (S/N) 2701 and below.
SB KS 271C-5 ALERT P/N: 600-01516-0051	Revision 1: February/2000	KS 271C Primary Servo Actuators, P/N 065-00179-XXXX (all versions), S/N 4201, 4158 through 4148, and 4103 and below.
SB KS 272C-4 ALERT P/N: 600-01518-0042	Revision 2: February/2000	KS 272C Trim Servo Actuators, P/N 065-00180-XXXX (all versions), S/N 2435 and below.

(b) Who must comply with this AD?: Anyone who wishes to operate an aircraft on the U.S. Register, where the aircraft incorporates one of the above-referenced autopilot servo actuators. These autopilot systems and autopilot servo actuators could be installed on, but not limited to, the following aircraft:

Type Certificate Holder	Aircraft Models	Autopilot Installed
Cessna Aircraft Company	172R, 172S, 182S, 206H, and T206H airplanes	Model KAP 140
Commander Aircraft Company	114B and 114TC airplanes	Model KFC 225
Mooney Aircraft Corporation	M20R and M20S airplanes	Model KFC 225
The New Piper Aircraft, Inc.	PA-28-181 airplanes	Model KAP 140
The New Piper Aircraft, Inc.	PA-46-350P airplanes	Model KFC 225
Raytheon Aircraft Company	Beech A36 airplanes, S/N E3157, E3218 through E3293, E3295, and E3297 through E3301	Model KFC 225
Raytheon Aircraft Company	Beech B36TC airplanes, S/N EA611, EA620, EA629 through EA649, and EA651	Model KFC 225
Raytheon Aircraft Company	Beech 58 airplanes, S/N TH1841, TH1870, TH1884 through TH1932, and TH1934	Model KFC 225

(c) What problem does this AD address?: The actions specified by this AD are intended to detect and correct a loose fastener in an autopilot servo actuator, which could cause the autopilot servo actuator to not disengage when power to the autopilot is removed. This could cause the pilot to experience additional control forces.

(d) What must I do to address this problem?: To address this problem, you must accomplish the following:

Action	When	In Accordance With
Inspect the autopilot servo actuator for a loose fastener.	Within 15 hours time-in-service after the effective date of this AD.	The applicable service information referenced in paragraph (a) of this AD.
Modify the autopilot servo actuator when a loose fastener is found.	Prior to further flight after the required inspection.	The applicable service information referenced in paragraph (a) of this AD.

(e) Is it permissible to just not use the autopilot since it is optional equipment?: You may do this provided you accomplish the following:

- (1) Check the primary flight controls for normal feel and motion and make any necessary adjustments;
 - (2) Pull and tie off the applicable circuit breakers as referenced in the Compliance section of the applicable service information referenced in paragraph (a) of this AD;
 - (3) Fabricate a placard, using letters of 1/8-inch in height, with the words "Autopilot Not Operational"; and
 - (4) Install this placard in the cockpit within the pilot's clear view.
- (f) Can I comply with this AD in any other way?: Yes.
- (1) You may use an alternative method of compliance or adjust the compliance time if:

- (i) Your alternative method of compliance provides an equivalent level of safety; and
- (ii) The Manager, Wichita Aircraft Certification Office (ACO), approves your alternative.

Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

(2) This AD applies to each aircraft identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For aircraft that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f)(1) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(g) Where can I get information about any already-approved alternative methods of compliance?: Contact Clyde Erwin, Aerospace Engineer, Wichita Aircraft Certification Office, FAA, 1801 Airport Road, Mid-Continent Airport, Wichita, Kansas 67209; telephone: (316) 946-4149; facsimile: (316) 946-4407.

(h) What if I need to fly the aircraft to another location to comply with this AD?: The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your aircraft to a location where you can accomplish the requirements of this AD.

(i) Are any service bulletins incorporated into this AD by reference?: Yes. Actions required by this AD must be done in accordance with Honeywell Service Bulletin No. SB KS 270C-4 ALERT, P/N: 600-01514-0041, Revision 1: February/2000, Honeywell Service Bulletin No. SB KS 271C-5 ALERT, P/N: 600-01516-0051, Revision 1: February/2000, or Honeywell Service Bulletin No. SB KS 272C-4 ALERT, P/N: 600-01518-0042, Revision 2: February/2000. The Director of the Federal Register approved this incorporation by reference under 5 U.S.C. 552(a) and 1 CFR part 51. You can get copies from Honeywell International Inc., 23500 West 105th Street, Olathe, Kansas 66061. You can look at copies at the FAA, Central Region, Office of the Regional Counsel, 901 Locust, Room 506, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

(j) When does this amendment become effective?: This amendment becomes effective on April 12, 2000.

FOR FURTHER INFORMATION CONTACT:

Clyde Erwin, Aerospace Engineer, Wichita Aircraft Certification Office, FAA, 1801 Airport Road, Mid-Continent Airport, Wichita, Kansas 67209; telephone: (316) 946-4149; facsimile: (316) 946-4407.

Issued in Kansas City, Missouri, on March 6, 2000.

Michael Gallagher, Manager, Small Airplane Directorate, Aircraft Certification Service.

**CESSNA AIRCRAFT COMPANY
AIRWORTHINESS DIRECTIVE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

2000-06-01 CESSNA AIRCRAFT COMPANY: Amendment 39-11641; Docket No. 97-CE-114-AD.

Applicability: All serial numbers of the following airplane models, certificated in any category, including those manufactured in France that have a capital "F" or "FR" prefix on the model number:

Models 150F, 150G, 150H, 150J, 150K, 150L, 150M, A150K, A150L, A150M, A-150L, A-A150L, F150F, F150G, F150H, F150J, F150K, F150L, F150M, FA150K, FA150L, FA150M, FRA150L, FRA150M, 152, A152, F152, FA152, 172F, 172G, 172H, 172I, 172K, 172L, 172M, 172N, 172P, 172Q, R172E (T41), R172F (T41), R172G (T41), R172H (T41), R172J, R172K, 172RG, F172F, F172G, F172H, F172K, F172L, F172M, F172N, F172P, FR172E, FR172F, FR172G, FR172H, FR172J, FR172K, 177, 177A, 177B, 177RG, F177RG, 180H, 180J, 180K, 182H, 182J, 182K, 182L, 182M, 182N, 182P, 182Q, 182R/T182, 182R, R182, R182/TR182, A182J, A182K, A182L, A182N, F182P, F182Q, FR182, 185D, 185E, A185E, A185F, 188, A188, 188A, A188A, 188B, A188B, T188C, A-A188B, U206, U206A, TU206A, U206B/TU206B, U206C/TU206C, U206D/TU206D, U206E/TU206E, U206F/TU206F, U206G/TU206G, P206, P206A, TP206A, P206B/TP206B, P206C/TP206C, P206D/TP206D, P206E/TP206E, 207/T207, 207A/T207A, 210E, 210F, 210G, 210H, 210J, 210K/T210K, 210L/T210L, 210M/T210M, 210N/T210N, T210F, T210G, T210H, T210J, P210N, 337, 337A, 337B/T337B, M337B, 337C/T337C, 337D/T337D, 337E/T337E, 337F, T337F, 337G, 337H/T337H, T337H-SP, T337G, P337H, F337E/FT337E, F337F/FT337F, F337G, F337H, FTB337, FT337GP, and FT337HP.

NOTE 1: This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if the unsafe condition has not been eliminated, the request should include specific proposed actions to address it.

Compliance: Required as indicated in the body of this AD.

To prevent foreign material from entering the fuel system and engine, which could result in loss of engine power or complete engine stoppage during flight, accomplish the following:

NOTE 2: This AD allows the aircraft owner or pilot to check the maintenance records to determine whether a Cessna part number (P/N) 0756005-2 top assembly, Cessna P/N 0756005-8 fuel strainer assembly, or a Cessna P/N 0756005-9 fuel strainer assembly was installed after December 12, 1996. Those parts that were shipped between December 12, 1996, and September 5, 1997, may have been manufactured with an internal tube installed to a depth less than specified and may become loose and dislodge from the strainer top assembly. See paragraph (c) of this AD for authorization.

(a) Within the next 12 calendar months after the effective date of this AD, unless already accomplished, measure the standpipe in the fuel strainer assembly (tube in the filter strainer top assembly) for a visible maximum length of 1.68 inches, in accordance with the ACCOMPLISHMENT INSTRUCTIONS section and Detail A in Cessna Single Engine Service Bulletin (SB) No. SEB97-9, dated November 17, 1997; or Cessna Multi-engine SB No. MEB97-12, dated November 17, 1997, whichever is applicable.

(b) If the standpipe does not measure a maximum length of 1.68 inches, prior to further flight, replace the filter strainer top assembly in accordance with the ACCOMPLISHMENT INSTRUCTIONS section in Cessna Single Engine SB No. SEB97-9, dated November 17, 1997; or Cessna Multi-engine SB No. MEB97-12, dated November 17, 1997, whichever is applicable.

(c) The owner/operator holding at least a private pilot certificate as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7) may check the maintenance records to determine whether a Cessna part number (P/N) 0756005-2 top assembly, Cessna P/N 0756005-8 fuel strainer assembly, or a Cessna P/N 0756005-9 fuel strainer assembly was installed after December 12, 1996. Those parts that were shipped between December 12, 1996, and September 5, 1997, may have been manufactured with an internal tube installed to a depth less than specified and may become loose and dislodge from the strainer top assembly. If, by checking the maintenance records, the owner/operator can make an absolute determination that one of these parts is not installed or was installed prior to December 12, 1996, the requirements of paragraphs (a) and (b) of this AD do not apply. The owner/operator must make an entry into the aircraft records showing compliance with this portion of the AD in accordance with section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).

(d) As of the effective date of this AD, no person may install, on any of the affected Cessna airplanes, a fuel filter assembly where the maximum length of the standpipe does not measure 1.68 inches.

(e) Special flight permits may be issued in accordance with sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate the airplane to a location where the requirements of this AD can be accomplished.

2000-06-01

(f) An alternative method of compliance or adjustment of the compliance time that provides an equivalent level of safety may be approved by the Manager, FAA, Wichita Aircraft Certification Office (ACO), 1801 Airport Road, Room 100, Wichita, Kansas 67209. The request shall be forwarded through an appropriate FAA Maintenance Inspector, who may add comments and then send it to the Manager, Wichita ACO.

NOTE 3: Information concerning the existence of approved alternative methods of compliance with this AD, if any, may be obtained from the Wichita ACO.

(g) The measurement and replacement required by this AD shall be done in accordance with Cessna Single Engine Service Bulletin (SB) No. SEB97-9, dated November 17, 1997, or Cessna Multi-engine SB No. MEB97-12, dated November 17, 1997. This incorporation by reference was approved by the Director of the Federal Register in accordance with 5 U.S.C. 552(a) and 1 CFR part 51. Copies may be obtained from the Cessna Aircraft Company, P. O. Box 7706, Wichita, Kansas 67277. Copies may be inspected at the FAA, Central Region, Office of the Regional Counsel, Room 506, 901 Locust, Kansas City, Missouri, or at the Office of the Federal Register, 800 North Capitol Street, NW, suite 700, Washington, DC.

(h) This amendment becomes effective on May 5, 2000.

FOR FURTHER INFORMATION CONTACT:

Paul O. Pendleton, Aerospace Engineer, FAA, Wichita Aircraft Certification Office, 1801 Airport Road, Room 100, Wichita, Kansas 67209; telephone: (316) 946-4143; facsimile: (316) 946-4407.

Issued in Kansas City, Missouri, on March 10, 2000.

Michael Gallagher, Manager, Small Airplane Directorate, Aircraft Certification Service.

**DORNIER LUFTFAHRT GMBH
AIRWORTHINESS DIRECTIVE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

2000-06-02 DORNIER LUFTFAHRT GMBH: Amendment 39-11642; Docket No. 99-CE-43-AD.

(a) What airplanes are affected by this AD?: Models Dornier 228-100, Dornier 228-101, Dornier 228-200, Dornier 228-201, Dornier 228-202, and Dornier 228-212 airplanes, all serial numbers, that are:

- (1) equipped with pneumatic deicing boots; and
- (2) certificated in any category.

(b) Who must comply with this AD?: Anyone who wishes to operate any of the above airplanes on the U.S. Register. The AD does not apply to your airplane if it is not equipped with pneumatic de-icing boots.

(c) What problem does this AD address?: The information necessary to activate the pneumatic wing and tail deicing boots at the first signs of ice accumulation is critical for flight in icing conditions. If we did not take action to include this information, flight crews could experience reduced controllability of the aircraft due to adverse aerodynamic effects of ice adhering to the airplane prior to the first deicing cycle.

(d) What must I do to address this problem?: To address this problem, you must revise the Limitations Section of the FAA-approved Airplane Flight Manual (AFM) to include the following requirements for activation of the ice protection systems. You must accomplish this action within the next 10 calendar days after the effective date of this AD, unless already accomplished. You may insert a copy of this AD in the AFM to accomplish this action:

“• Except for certain phases of flight where the AFM specifies that deicing boots should not be used (e.g., take-off, final approach, and landing), compliance with the following is required.

- Wing and Tail Leading Edge Pneumatic Deicing Boot System, if installed, must be activated:
 - At the first sign of ice formation anywhere on the aircraft, or upon annunciation from an ice detector system, whichever occurs first; and
 - The system must either be continued to be operated in the automatic cycling mode, if available; or the system must be manually cycled as needed to minimize the ice accretions on the airframe.
- The wing and tail leading edge pneumatic deicing boot system may be deactivated only after:
 - Leaving known or observed/detected icing that the flight crew has visually observed on the aircraft or was identified by the on-board sensors; and
 - After the airplane is determined to be clear of ice.”

NOTE: The FAA recommends periodic treatment of deicing boots with approved ice release agents, such as ICEX™, in accordance with the manufacturer's application instructions.

(e) Can the pilot accomplish the action?: Yes. Anyone who holds at least a private pilot certificate, as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7), may incorporate the AFM revisions required by this AD. You must make an entry into the aircraft records that shows compliance with this AD, in accordance with section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).

(f) Can I comply with this AD in any other way?: Yes.

(1) You may use an alternative method of compliance or adjust the compliance time if:

- (i) Your alternative method of compliance provides an equivalent level of safety; and
- (ii) The Manager, Small Airplane Directorate, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager.

(2) This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f)(1) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(g) Where can I get information about any already-approved alternative methods of compliance?: Contact the Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4121; facsimile: (816) 329-4091.

(h) What if I need to fly the airplane to another location to comply with this AD?: The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(i) When does this amendment become effective?: This amendment becomes effective on May 5, 2000.

FOR FURTHER INFORMATION CONTACT: Mr. John P. Dow, Sr., Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 506, Kansas City, Missouri 64106; telephone: (816) 329-4121; facsimile: (816) 329-4090.

Issued in Kansas City, Missouri, on March 10, 2000.

Michael Gallagher, Manager, Small Airplane Directorate, Aircraft Certification Service.

**BOMBARDIER INC
AIRWORTHINESS DIRECTIVE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

2000-06-03 BOMBARDIER INC.: Amendment 39-11643; Docket No. 99-CE-44-AD.

(a) What airplanes are affected by this AD?: Models DHC-6-1, DHC-6-100, DHC-6-200, DHC-6-300 airplanes, all serial numbers, that are:

- (1) Equipped with pneumatic deicing boots; and
- (2) Certificated in any category.

(b) Who must comply with this AD?: Anyone who wishes to operate any of the above airplanes on the U.S. Register. The AD does not apply to your airplane if it is not equipped with pneumatic de-icing boots.

(c) What problem does this AD address?: The information necessary to activate the pneumatic wing and tail deicing boots at the first signs of ice accumulation is critical for flight in icing conditions. If we did not take action to include this information, flight crews could experience reduced controllability of the aircraft due to adverse aerodynamic effects of ice adhering to the airplane prior to the first deicing cycle.

(d) What must I do to address this problem?: To address this problem, you must revise the Limitations Section of the FAA-approved Airplane Flight Manual (AFM) to include the following requirements for activation of the ice protection systems. You must accomplish this action within the next 10 calendar days after the effective date of this AD, unless already accomplished. You may insert a copy of this AD in the AFM to accomplish this action:

“• Except for certain phases of flight where the AFM specifies that deicing boots should not be used (e.g., take-off, final approach, and landing), compliance with the following is required.

- Wing and Tail Leading Edge Pneumatic Deicing Boot System, if installed, must be activated:
 - At the first sign of ice formation anywhere on the aircraft, or upon annunciation from an ice detector system, whichever occurs first; and
 - The system must either be continued to be operated in the automatic cycling mode, if available; or the system must be manually cycled as needed to minimize the ice accretions on the airframe.
- The wing and tail leading edge pneumatic deicing boot system may be deactivated only after:
 - Leaving known or observed/detected icing that the flight crew has visually observed on the aircraft or was identified by the on-board sensors; and
 - After the airplane is determined to be clear of ice.”

NOTE: The FAA recommends periodic treatment of deicing boots with approved ice release agents, such as ICEX™, in accordance with the manufacturer's application instructions.

(e) Can the pilot accomplish the action?: Yes. Anyone who holds at least a private pilot certificate, as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7), may incorporate the AFM revisions required by this AD. You must make an entry into the aircraft records that shows compliance with this AD, in accordance with section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).

(f) Can I comply with this AD in any other way?: Yes.

(1) You may use an alternative method of compliance or adjust the compliance time if:

- (i) Your alternative method of compliance provides an equivalent level of safety; and
- (ii) The Manager, Small Airplane Directorate, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager.

(2) This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f)(1) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(g) Where can I get information about any already-approved alternative methods of compliance?: Contact the Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4121; facsimile: (816) 329-4091.

(h) What if I need to fly the airplane to another location to comply with this AD?: The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(i) When does this amendment become effective?: This amendment becomes effective on May 5, 2000.

FOR FURTHER INFORMATION CONTACT:

Mr. John P. Dow, Sr., Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 506, Kansas City, Missouri 64106; telephone: (816) 329-4121; facsimile: (816) 329-4090.

Issued in Kansas City, Missouri, on March 10, 2000.

Michael Gallagher, Manager, Small Airplane Directorate, Aircraft Certification Service.

**FAIRCHILD AIRCRAFT CORPORATION
AIRWORTHINESS DIRECTIVE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

2000-06-04 FAIRCHILD AIRCRAFT CORPORATION.: Amendment 39-11644; Docket No. 99-CE-52-AD.

(a) What airplanes are affected by this AD?: Models SA226-T, SA226-AT, SA226-T(B), SA227-AT, SA227-TT, SA226-TC, SA227-AC, SA227-PC, SA227-BC, SA227-CC, SA227-DC airplanes, all serial numbers, that are:

- (1) Equipped with pneumatic deicing boots; and
- (2) Certificated in any category.

(b) Who must comply with this AD?: Anyone who wishes to operate any of the above airplanes on the U.S. Register. The AD does not apply to your airplane if it is not equipped with pneumatic de-icing boots.

(c) What problem does this AD address?: The information necessary to activate the pneumatic wing and tail deicing boots at the first signs of ice accumulation is critical for flight in icing conditions. If we did not take action to include this information, flight crews could experience reduced controllability of the aircraft due to adverse aerodynamic effects of ice adhering to the airplane prior to the first deicing cycle.

(d) What must I do to address this problem?: To address this problem, you must revise the Limitations Section of the FAA-approved Airplane Flight Manual (AFM) to include the following requirements for activation of the ice protection systems. You must accomplish this action within the next 10 calendar days after the effective date of this AD, unless already accomplished. You may insert a copy of this AD in the AFM to accomplish this action:

“• Except for certain phases of flight where the AFM specifies that deicing boots should not be used (e.g., take-off, final approach, and landing), compliance with the following is required.

- Wing and Tail Leading Edge Pneumatic Deicing Boot System, if installed, must be activated:
 - At the first sign of ice formation anywhere on the aircraft, or upon annunciation from an ice detector system, whichever occurs first; and
 - The system must either be continued to be operated in the automatic cycling mode, if available; or the system must be manually cycled as needed to minimize the ice accretions on the airframe.
- The wing and tail leading edge pneumatic deicing boot system may be deactivated only after:
 - Leaving known or observed/detected icing that the flight crew has visually observed on the aircraft or was identified by the on-board sensors; and
 - After the airplane is determined to be clear of ice.”

NOTE: The FAA recommends periodic treatment of deicing boots with approved ice release agents, such as ICEX™, in accordance with the manufacturer's application instructions.

(e) Can the pilot accomplish the action?: Yes. Anyone who holds at least a private pilot certificate, as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7), may incorporate the AFM revisions required by this AD. You must make an entry into the aircraft records that shows compliance with this AD, in accordance with section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).

(f) Can I comply with this AD in any other way?: Yes.

(1) You may use an alternative method of compliance or adjust the compliance time if:

- (i) Your alternative method of compliance provides an equivalent level of safety; and
- (ii) The Manager, Small Airplane Directorate, approves your alternative. Submit your request through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager.

(2) This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f)(1) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(g) Where can I get information about any already-approved alternative methods of compliance?: Contact the Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4121; facsimile: (816) 329-4091.

(h) What if I need to fly the airplane to another location to comply with this AD?: The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(i) When does this amendment become effective?: This amendment becomes effective on May 5, 2000.

FOR FURTHER INFORMATION CONTACT:

Mr. John P. Dow, Sr., Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 506, Kansas City, Missouri 64106; telephone: (816) 329-4121; facsimile: (816) 329-4090.

Issued in Kansas City, Missouri, on March 10, 2000.

Michael Gallagher, Manager, Small Airplane Directorate, Aircraft Certification Service.

**THE NEW PIPER AIRCRAFT INC
AIRWORTHINESS DIRECTIVE
SMALL AIRCRAFT, ROTORCRAFT, GLIDERS, BALLOONS, & AIRSHIPS**

2000-06-06 THE NEW PIPER AIRCRAFT, INC.: Amendment 39-11646; Docket No. 99-CE-49-AD.

(a) What airplanes are affected by this AD? PA-31, PA-31-300, PA-31-325, PA-31-350, PA-31P, PA-31T, PA-31T1, PA-31T2, PA-31T3, and PA-31P-350 airplanes, all serial numbers, that are:

- (1) equipped with pneumatic deicing boots; and
- (2) certificated in any category.

(b) Who must comply with this AD? Anyone who wishes to operate any of the above airplanes on the U.S. Register. The AD does not apply to your airplane if it is not equipped with pneumatic de-icing boots.

(c) What problem does this AD address? The information necessary to activate the pneumatic wing and tail deicing boots at the first signs of ice accumulation is critical for flight in icing conditions. If we did not take action to include this information, flight crews could experience reduced controllability of the aircraft due to adverse aerodynamic effects of ice adhering to the airplane prior to the first deicing cycle.

(d) What must I do to address this problem? To address this problem, you must revise the Limitations Section of the FAA-approved Airplane Flight Manual (AFM) to include the following requirements for activation of the ice protection systems. You must accomplish this action within the next 10 calendar days after the effective date of this AD, unless already accomplished. You may insert a copy of this AD in the AFM to accomplish this action:

“• Except for certain phases of flight where the AFM specifies that deicing boots should not be used (e.g., take-off, final approach, and landing), compliance with the following is required.

- Wing and Tail Leading Edge Pneumatic Deicing Boot System, if installed, must be activated:

- At the first sign of ice formation anywhere on the aircraft, or upon annunciation from an ice detector system, whichever occurs first; and

- The system must either be continued to be operated in the automatic cycling mode, if available; or the system must be manually cycled as needed to minimize the ice accretions on the airframe.

- The wing and tail leading edge pneumatic deicing boot system may be deactivated only after:

- leaving known or observed/detected icing that the flight crew has visually observed on the aircraft or was identified by the on-board sensors; and

- after the airplane is determined to be clear of ice.”

NOTE: The FAA recommends periodic treatment of deicing boots with approved ice release agents, such as ICEX™, in accordance with the manufacturer's application instructions.

(e) Can the pilot accomplish the action? Yes. Anyone who holds at least a private pilot certificate, as authorized by section 43.7 of the Federal Aviation Regulations (14 CFR 43.7), may incorporate the AFM revisions required by this AD. You must make an entry into the aircraft records that shows compliance with this AD, in accordance with section 43.9 of the Federal Aviation Regulations (14 CFR 43.9).

(f) Can I comply with this AD in any other way? Yes.

(1) You may use an alternative method of compliance or adjust the compliance time if:

- (i) Your alternative method of compliance provides an equivalent level of safety; and
- (ii) The Manager, Small Airplane Directorate, approves your alternative. Submit your request

through an FAA Principal Maintenance Inspector, who may add comments and then send it to the Manager.

(2) This AD applies to each airplane identified in the preceding applicability provision, regardless of whether it has been modified, altered, or repaired in the area subject to the requirements of this AD. For airplanes that have been modified, altered, or repaired so that the performance of the requirements of this AD is affected, the owner/operator must request approval for an alternative method of compliance in accordance with paragraph (f)(1) of this AD. The request should include an assessment of the effect of the modification, alteration, or repair on the unsafe condition addressed by this AD; and, if you have not eliminated the unsafe condition, specific actions you propose to address it.

(g) Where can I get information about any already-approved alternative methods of compliance? Contact the Small Airplane Directorate, 901 Locust, Room 301, Kansas City, Missouri 64106; telephone: (816) 329-4121; facsimile: (816) 329-4091.

(h) What if I need to fly the airplane to another location to comply with this AD? The FAA can issue a special flight permit under sections 21.197 and 21.199 of the Federal Aviation Regulations (14 CFR 21.197 and 21.199) to operate your airplane to a location where you can accomplish the requirements of this AD.

(i) When does this amendment become effective? This amendment becomes effective on May 5, 2000.

FOR FURTHER INFORMATION CONTACT:

Mr. John P. Dow, Sr., Aerospace Engineer, FAA, Small Airplane Directorate, 901 Locust, Room 506, Kansas City, Missouri 64106; telephone: (816) 329-4121; facsimile: (816) 329-4090.

Issued in Kansas City, Missouri, on March 17, 2000.

Carolanne L. Cabrini, Acting Manager, Small Airplane Directorate, Aircraft Certification Service.